



# LBS

STUD WELDING UNITS FOR CAPACITOR DISCHARGE STUD WELDING



COMPACT  
AND ROBUST  
CONSTRUCTION

CHARGING VOLTAGE  
CONTINUOUSLY ADJUSTABLE

INDICATION OF ALL  
FUNCTIONS BY CLEARLY  
ARRANGED LED

VERY EASY  
OPERATION



ELECTRONICALLY CLOCKED  
INVERTER CHARGING BOARD

LOW-LOSS CHARGING  
OF CAPACITORS

VERY SHORT CHARGING TIMES AND  
THUS QUICK WELDING SEQUENCES

THE UNITS LBS 90 AND LBS 130  
CAN OPTIONALLY BE EQUIPPED  
WITH A SECOND CHARGING  
BOARD FOR ESPECIALLY FAST  
CHARGING TIMES.



## HIGHLIGHTS AND SPECIAL EQUIPMENT



### ELECTRONICALLY CLOCKED INVERTER CHARGING BOARDS

- » ensure very short charging times and thus quick welding sequences
- » ensure energy-efficient charging of capacitors
- » The units LBS 90 and LBS 130 can optionally be equipped with a second charging board for especially fast charging times. Thus, extremely quick welding sequences (e.g. for automatic applications) can be achieved.

# VERY SHORT CHARGING TIMES! QUICK WELDING SEQUENCES!

## TECHNICAL DATA AND CHARACTERISTICS

	LBS 44	LBS 75	LBS 80	LBS 90	LBS 130
<b>Max. welding diameter (mm)</b>	6	8	10	10	10
<b>Capacitance (µF)</b>	44000	66000	90000	88000	132000
<b>Charging voltage (V)</b>	60 - 200	60 - 200	60 - 200	60 - 200	60 - 200
<b>Welding time (mS)</b>	1 - 3	1 - 3	1 - 3	1 - 3	1 - 3
<b>Electronically clocked inverter charging boards</b>					
1 charging board	x	x	x	x	x
2 charging boards				0	0
<b>Operation</b>					
Repeat cycle lock	x	x	x	x	x
Electronic function control	x	x	x	x	x
Self diagnosis system	x	x	x	x	x
Automatic function test	x	x	x	x	x
<b>Error diagnosis systems</b>					
Excess temperature	x	x	x	x	x
Damage on welding/control cable	x	x	x	x	x
Damage on solenoid	x	x	x	x	x
<b>Thermic controlled ventilator</b>			x	x	x

	<b>LBS 44</b>	<b>LBS 75</b>	<b>LBS 80</b>	<b>LBS 90</b>	<b>LBS 130</b>
<b>Robust, powder-coated metal housing</b>	x	x	x	x	x
<b>Dimensions</b>					
Width (mm)	195	195	195	275	275
Height (mm)	260	260	260	260	260
Length (mm)	400	400	400	400	400
Weight (kg)	10	11	13,5	19	20
<b>Electric connection</b>					
Mains supply (V) at 50/60 Hz	230 (115)	230 (115)	230 (115)	230 (115)	230 (115)
Mains fuse external	≥ 10 AT	≥ 10 AT	≥ 10 AT	≥ 10 AT	≥ 10 AT
Protection	IP 21	IP 21	IP 21	IP 21	IP 21
<b>Control cable socket for welding guns</b>	7-pin	7-pin	7-pin	7-pin	7-pin
<b>Suitable welding guns</b>					
PKM-1B	x	x	x	x	x
PHM-1A	x	x	x	x	x
PIM-1B	x	x	o		

x – Standard, o – Option



## Bolte GmbH

Flurstraße 25  
D-58285 Gevelsberg

Tel.: +49 (0)2332 55106-0  
Fax: +49 (0)2332 55106-11

Ohmstraße 3  
D-85221 Dachau

Tel.: +49 (0)8131 5159-0  
Fax: +49 (0)8131 5159-11

E-Mail: [info@bolte.gmbh](mailto:info@bolte.gmbh)



[www.bolte.gmbh](http://www.bolte.gmbh)